

PCN Overview				
PCN Number		DHCOR-iMX6ULL-005		
PCN Date		26.04.2021		
Type of Change		Change Component		
History				
Revision	Date	Description	Name	
R01	26.04.2021	First draft	AG	
R01	05.05.2021	Revied and released (#8988)	HH	

Change Information	
Reason of Change	Newer production lots (see NXP customer information 201908013I below) of the NXP i.MX6ULL, cause stability problems on our DHCOR i.MX6ULL module in rare cases. Customer Information Notification 201908013I from NXP: NXP Semiconductors announces the Final Test site expansion for the i.MX6ULL and i.MX6UltraLite product associated with this notification, from the current NXP-ATTJ Tianjin, China Final Test site to the ASE, Chung-Li, Taiwan Final Test site. Final Test site expansion was successfully qualified adhering to NXP specifications.
Description of Changes	One of the i.MX6ULL VDD_SOC_CAP capacitors at our DHCOR i.MX6ULL module was changed from 22uF to 47uF. This change improves the system stability under high CPU load.
Customer Impact	-
Suggested Measures	None, but please also consider the customer information DOC_DHCOR-iMX6ULL-001_R01_2020-12-16.pdf if you are using the 792 MHz i.MX6ULL CPU from NXP.
Logistics	-

Affected Products	
HI00067	DHCR-iMX6ULL-C052-R025-SPI-C-01LG
HI00072	DHCR-iMX6ULL-C080-R051-SPI-WBT-I-01LG
HI00076	DHCM-iMX6ULL-C052-R025-F0409-SPI-E-RTC-C-01D2
HI00077	DHCM-iMX6ULL-C052-R025-F0012-SPI-E-SD-RTC-C-01D2
HI00084	DHCM-iMX6ULL-C090-R051-F0409-SPI-E-CAN2-RTC-WBT-C-01D2

HI00089	DHCM-iMX6ULL-C080-R051-F0409-SPI-E2-CAN2-RTC-WBT-ADC-I-01D2
HI00090	DHCM-iMX6ULL-C080-R051-F0409-SPI-E2-CAN2-SD-RTC-ADC-I-01D2

Contacts	
Technical Contact	Tel: +49 8662 4882 0 Mail: support@dh-electronics.com
Sales Contact	Tel: +49 8662 4882 0 Mail: sales@dh-electronics.com