PCN Overv	iew		electronics
PCN Number		DHCOM-STM32MP15-003	
PCN Date		22.05.2023	
Type of Change		Change Software	
History			
Revision	Date	Description	Name
R01	16.05.2023	First draft	AG
R01	22.05.2023	Reviewed and released	AB

Change Information			
Reason of Change	Outdated U-Boot Version 2020.07. In the meantime, many fixes and changes are included in up-to-date U-Boot ver- sion for the DHCOM STM32MP15. With the old 2020.07 based U-Boot version e.g., ethernet is no longer working in combination with up-to-date Linux version and also SD card boot is not possible.		
Description of Changes	All DHCOM STM32MP15 based system on modules are shipped with pre-pro- grammed U-Boot version 2020.07. With this change the U-Boot version will be up- dated to 2022.07. The sources can be found at the following link: <u>https://github.com/dh-electronics/u-boot-stm32mp1/tree/v2022.07_testbench</u>		
Customer Impact	Updated pre-programmed U-Boot binary to version 2022.07.		
Suggested Measures	It should be checked whether the pre-programmed binary works in the production and series process. Depending on the customer, the pre-programmed bootloader is used or a special version is installed by the customer. If the pre-programmed version is used, the customer must check, if this new version works also with the currently used pro- duction image. If special version is installed during production, the customer must ensure, that the update from new 2022.07 works without any issues.		
Logistics	Please ask your sales contact, if you have questions regarding this change sce- nario.		

Affected Products			
HS00014	DHCM-STM32MP157C-C065-R102-F0819-SPI-E2-CAN2-SDR104-RTC-WBT-T-DSI-I-01D2		
HS00015	DHCM-STM32MP157C-C065-R102-F0819-SPI-E-CAN2-SD-RTC-T-DSI-I-01D2		
HS00016	DHCM-STM32MP153C-C065-R102-F0819-SPI-E2-CAN2-RTC-I-01D2		
HS00017	DHCM-STM32MP153C-C065-R051-F0819-SPI-E-CAN2-I-01D2		
HS00019	DHCM-STM32MP157C-C065-R102-F0819-SPI-E-CAN2-SD-RTC-T-DSI-I-01D2-microSDboot		
HS00024	DHCM-STM32MP157C-C065-R102-F0409-SPI-E-RTC-T-I-01D2		
HS00029	DHCM-STM32MP157C-C065-R051-F0409-SPI-E2-SD-RTC-WBT-I-01D2		
FS00013	DHCM-STM32MP153C-C065-R102-F0819-SPI-E2-CAN2- RTC-I-01D2		
FS00014	DHCM-STM32MP153C-C065-R102-F0819-SPI-E2-CAN2- RTC-I-01D2		

Contacts		
Technical Contact	Tel: +49 8662 4882 0	
	Mail: support@dh-electronics.com	
Sales Contact	Tel: +49 8662 4882 0	
	Mail: sales@dh-electronics.com	