

PCN Overview				
PCN Number		DHCOM-iMX6-011		
PCN Date		18.07.2022		
Type of Change		Change PCB		
History				
Revision	Date	Description	Name	
R01	18.07.2022	First draft	AB	
R01	18.07.2022	Approved & Released	AG	

Change Information	
Reason of Change	End of life of the used Adress Latch TI# SN74LVC573AZQNR
Description of Changes	Redesign of the PCB due to end of life of the used Adress Latch TI# SN74LVC573AZQNR New PCB-Version: 493-500
Customer Impact	Old PCB-Versions will become obsolete. Change to the new PCB-Version will also change the article number of the module.
Suggested Measures	DH advises customers to carefully validate the new product version before their production release.
Logistics	Please ask your sales contact if you have any questions about this change.

Affected Products		
Old Version	New Version	Description
HI00029	HI00101	DHCM-iMX6DL-C080-R102-F0819-E-SD-RTC-T-HS-I-01D2
HI00041	HI00101	DHCM-iMX6DL-C080-R102-F0819-E-SD-RTC-T-HS-I-01D2
HI00045	HI00102	DHCM-iMX6Q-C080-R102-F0819-E-SD-RTC-T-HS-I-01D2
HI00046	HI00103	DHCM-iMX6S-C080-R051-F0819-E-SD-RTC-T-HS-I-01D2
HI00033	HI00108	DHCM-iMX6S-C080-R051-F0051-E-I-01D2
HI00037	HI00109	DHCM-iMX6S-C080-R051-F0409-E-T-I-01D2
HI00042	HI00110	DHCM-iMX6S-C080-R102-F0409-E-RTC-T-I-01D2
HI00047	HI00111	DHCM-iMX6D-C080-R102-F0409-E-I-01D2
HI00049	HI00112	DHCM-iMX6S-C080-R051-F0819-E-SD-RTC-I-01D2-Coating
HI00053	HI00113	DHCM-iMX6S-C080-R051-F0819-E-I-01D2
HI00054	HI00114	DHCM-iMX6Q-C080-R204-F0819-E-RTC-I-01D2
HI00055	HI00115	DHCM-iMX6S-C080-R102-F0409-E-CAN2-RTC-I-01D2
HI00078	HI00116	DHCM-iMX6Q-C080-R102-F0819-E-CAN2-RTC-HS-I-01D2

Contacts	
Technical Contact	Tel: +49 8662 4882 0 Mail: support@dh-electronics.com
Sales Contact	Tel: +49 8662 4882 0 Mail: sales@dh-electronics.com